

~~TOP SECRET~~

~~PRIORITY~~

OUT58366

P 282335Z  
FM NPIC

1966 APR 28 23 57Z  
25X1

~~TOP SECRET~~

CITE NPIC 7055.

25X1

ATTN: DIAAP-IP

DIAMS-3C

DIAXX-3C4

1. AS PER REQUEST, THE FOLLOWING ANOMALY DATA CONCERNING MISSION 4027 KNOWN AT THIS TIME, IS LISTED BELOW. SHOULD OTHER PERTINENT CHANGES BE DISCOVERED DURING THE TECHNICAL PROCESSING AT THIS SITE, THEY WILL BE FORWARDED ASAP.

2. KNOWN, PERTINENT OCCURRENCES ARE AS FOLLOWS:

29 APR 1966

A. UNEXPOSED FILM

1. REV. 21: FRAMES 1, 2, 9, 10, AND 11 (1 AND 2 EDITED;  
9-11 DOOR FAILURE)

2. REV. 23: FRAMES 7 AND 8 (DOOR FAILURE)

3. REV. 37: FRAMES 5, 6, 7, AND 8 (DOOR FAILURE)

4. REV. 45: FRAMES 8 AND 9 (DOOR FAILURE)

5. REV. 46: FRAMES 12, 13, 14, AND 15 (DOOR FAILURE)

B. FILM WITH DUBIOUS IMAGERY

1. REV. 64: FRAMES 1 AND 2 (SET JOG AND PROCESSING BLANK)


2. REV. 82: FRAME 1 (PRE-REV. WRAP-UP)

C. TITLING

1. REVS. CONTAINING ANY FRAMES OR STRIPS (WHETHER CONTINUOUS COVERAGE OR NOT) WHICH CONTAIN ASCENDING AND DESCENDING (LATITUDE-

25X1

~~TOP SECRET~~



-2-

WISE) MATERIAL, IS GIVEN THE SUFFIX "M", MEANING "MIXED". THIS IS DONE FOR THE ENTIRE REV. ALL OTHERS ARE TITLED "D".

2. THOSE REVS. WHICH WERE GIVEN "M" TITLING ARE AS FOLLOWS:

7, 9, 11, 13, 14, 21, 23, 24, 25, 28, 29, 30, 31, 40, 41, 44, 45, 46, 47, 57, 58, 60, 61, 62, 63, 73, 74, 76, 77, 78, 79, 80, 87, 90, 94, AND 95.

D. SLIT PROBLEM

1. A SLIT PROBLEM IN COMMAND SELECTION ON HEALTH CHECK WAS FOUND. THEREFORE, REVS. 4 THUR 22, SLIT NR. 1 WITH A SUN ANGLE CUT-OFF SET AT 9 DEGREES WAS USED.

2. FROM REVS. 22 TO 95, SLIT NR. 1 AND NR. 3 WERE SELECTED AS REQUIRED, WITH A SUN ANGLE CUT-OFF OF ABOUT 0 DEGREES, SLIT 2 WAS NOT USED AT ALL.

E. CHANGES TO THE MCD LIST

1. REV. 89, FRAME 6

CHANGE	TO	LINES
3F	1F	19
ROLL 32.614	30.487	19
S/I ROLL 32.610	30.500	21 AND 34

2. REV. 89, FRAME 7

CHANGE	TO	LINES
3A	1A	19
S/I ROLL 32.610	30.500	21 AND 34

3. REV. 89, FRAME 17

CHANGE	TO	LINES
--------	----	-------

-3-

S/I ROLL 10.630 4.200 21 AND 34

(ADD TGT. 8C0010 TO ACTUAL) 24

4. REV. 89, FRAME 18

CHANGE	TO	LINES
--------	----	-------

S/I ROLL 10.630	4.200	21 AND 24
-----------------	-------	-----------

3A	1A	19
----	----	----

5. REV. 89, FRAME 23

CHANGE	TO	LINES
--------	----	-------

3F	1F	19
----	----	----

ROLL MINUS 5.672 MINUS 15.598 19

(ALL OF LINE 20 IS INCORRECT) 20

S/I ROLL MINUS 5.670 MINUS 15.598 21 AND 34

6. REV. 89, FRAME 24

CHANGE	TO	LINES
--------	----	-------

3A	1A	19
----	----	----

S/I ROLL MINUS 5.670 MINUS 15.670 21 AND 34

7. REV. 92

ADD FRAMES 25 THRU 28, PRIMARY AND S/I. AN UP-DATED  
COMPUTER RUN CONTAINING THE POSITIONING AND TARGET DATE  
FOR THESE FRAMES TO BE TRANSMITTED VIA DLT/1004 ASAP.

8. REV. 96: FRAMES 1 AND 2 (INDEX CAMERA)

EXTRA FRAMES EXPOSED DURING RECOVERY CYCLE.

GP-1

T O P S E C R E T

--END OF MESSAGE--